

AE/LSGD/PLPV/4/2021-22

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Amrita Vidyalayam, Pulpally
P.O. Pulpally, Sulthan Bathery

Permanent
multistoreyed - 2003

2021-2022

GF 2x 6.40 x 6.70 x 3.40 → Class
 1x 13.20 x 6.30 x 3.40 → Lab
 2x 6.40 x 6.70 x 3.40 → Office
 1x 9.90 x 6.30 x 3.40 → Principal room

F.F. 9x 6.40 x 6.70 x 3.45 → Class
 2x 13.20 x 6.30 x 3.40 → Lab
 1x 13.20 x 6.30 x 3.40 → Library

S.F. 11x 6.40 x 6.70 x 3.40 → Class
 1x 13.20 x 6.30 x 3.40 → Lab
 1x 6.40 x 6.70 x 3.40 → Guest room
 1x 6.40 x 6.70 x 3.40 → Staff room

NIL

Yes
Sound under normal wind climatic conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 26/06/21 and found to be fit / unfit to conduct classes, for the period 2021-22 year for the reasons stated above.

Place: Pulpally
Date: 07/06/21



[Signature]
Assistant Engineer
ASSISTANT ENGINEER
L S G D Section
Pulpally Gramapanchayath
Phone: 0471 241231